



## Caution When Applying Paint to New Asphalt

Products. Service. Knowledge.

---

### Corporate Offices

8081 Philips Hwy  
Suite 22  
Jacksonville, FL 32256  
Ph: 904-448-4074  
Fx: 904-448-4076

8/27/10

To Contractors and Property Managers and Owners:

### Florida Distribution Center

9556 Historic Kings Road South,  
#315  
Jacksonville, FL 32257  
Ph: 904.733.2121  
Fx: 904.733.8800  
Toll Free: 888.717.7771

Caution should be taken when applying painted pavement markings to new asphalt. Applying paints to new asphalt that has not had time to sufficiently cure will likely result in cracking of the asphalt surface and delamination of the paint.

There are many contributing factors that cause this effect. However the risks are much greater in high surface and ambient temperature ranges, thick paint applications, fine aggregate asphalt mix and lack of traffic and rain on the asphalt surface.

### Orlando Branch

6441 Pinecastle Boulevard  
Orlando, FL 32809  
Ph: 407.888.2080  
Fx: 407.888.2425

It is ours and industry recommendations that the above factors are considered when applying paints. There are a few methods or conditions to avoid or lessen the risk asphalt surface damage.

1. Allow asphalt to cure for a minimum of 30 days.
2. Apply painted pavement markings in two separate thinner applications over an extended period of time.
3. Do not apply painted pavement markings when surface temperatures are recurrently above 110 degrees F.
4. Do not apply painted pavement markings when there will be an extended period of time between application and regular traffic.

### Miami Branch

10250 NW 89<sup>th</sup> Ave., #1  
Medley, FL 32809  
Ph: 305.885.4274  
Fx: 305.885.4273

Understandably, some methods are not possible due to construction schedules. Nevertheless, any listed method or condition that is utilized will lessen the risk. Note that you may have your contractor test an area before striping. However, the test area and time may not be representative of the entire project, thus potentially providing false results.

### Charlotte Branch

1955 Scott Futrell Drive  
Charlotte, NC 28208  
Ph: 704.697.9577  
Fx: 704.697.9576

If you have further questions regarding this issue, you are welcome to contact me personally or look on our website ([www.ppcatalog.com](http://www.ppcatalog.com)) for more details on the causes and effect of painted pavement markings on new asphalt.

### Raleigh-Durham Branch

200 Travis Park  
Cary, NC 27511  
Ph: 919.851.0799  
Fx: 919.851.1294

Sincerely,

*Gregory W. Driskell*

Gregory W. Driskell  
President

### Texas Distribution Center

3377 West 11<sup>th</sup> Street  
Houston, TX 77008  
Ph: 713.864.0906  
Fx: 713.864.0833  
Toll Free: 888.717.7773